STATE	STATE PROJECT REFERENCE NO.	MIST	SMIN!
N.C.	17BP.8.R.18	1	17

STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION **DIVISION OF HIGHWAYS** GEOTECHNICAL ENGINEERING UNIT

STRUCTURE SUBSURFACE INVESTIGATION

	PROJ. REFERENCE NO. <u>17BP.8.R.7</u> F.A. PROJ. <u>SF-520036</u> COUNTY <u>LEE</u>	
E.	PROJECT DESCRIPTION	_
	SITE DESCRIPTION BRIDGE ON SR-1162 (SHERIFF WATSON RD.) OVER JUNIPER CREEK	_
CONTI		PERSONNEL B. KEANEY
SHEET 1	<u>DESCRIPTION</u> TITLE SHEET	
2.2A	LEGEND	M. BATTEN
3		E. HOWEY
4		D. TIGNOR
5-8	BORE LOGS	D. HGNOR
9-10	FIELD SCOUR REPORT	=
11-12	SITE PHOTOGRAPHS	
13-17	FOUNDATION RECOMMENDATIONS	
-		
5		
≘	envestigated by	F&R, Inc.
÷.	\$	B, KEANEY
Ξ		
=	SUBMITTED BY	HDR, Inc.
3 8	DATE	July 30, 2012

CAUTION NOTICE

THE SUBSURFACE INFORMATION AND THE SUBSURFACE INVESTIGATION ON WHICH IT IS BASED WERE MADE FOR THE PURPOSE OF STUDY, PLANNING, AND DESIGN, AND NOT FOR CONSTRUCTION OR PAY PURPOSES. THE VARIOUS FIELD BORING LOGS, ROCK CORES, AND SOIL TEST DATA AVAILABLE MAY BE REVIEWED OR INSPECTED IN RALEIGH BY CONTACTING THE N. C. DEPARTMENT OF TRANSPORTATION, GEOTECHNICAL ENGINEERING UNIT AT 1991 250-4088, NEITHER THE SUBSURFACE PLANS AND REPORTS, NOR THE FIELD BORING LOGS, ROCK CORES, OR SOIL TEST DATA ARE PART OF THE CONTRACT.

GENERAL SOL AND ROCK STRATA DESCRIPTIONS AND INDICATED BOUNDARIES ARE BASED ON A GEOTECHNICAL INTERPRETATION OF ALL AVAILABLE SUBSURFACE DATA AND MAY NOT NECESSABILY REFLECT THE ACTUAL SUBSURFACE CONDITIONS BETWEEN BORINGS OR BETWEEN SAMPLED STRATA WITHIN THE BOREHOLE, THE LABORATORY SAMPLE DATA AND THE IN SITU (IN-PLACE) TEST DATA CAN BE RELIED ON ONLY TO THE DECREE OF RELIABILITY INHERENT IN THE STANDARD TEST METHOD, THE OBSERVED WATER LEVELS OR SOL MOISTURE CONDITIONS INDICATED IN THE SUBSURFACE INVESTIGATION ARE AS RECORDED AT THE TIME OF THE INVESTIGATION, THESE WATER LEVELS OR SOL MOISTURE CONDITIONS MAY VARY CONSIDERABLY WITH TIME ACCORDING TO CLIMATIC CONDITIONS INCLUDING TEMPERATURES, PRECIPITATION, AND WIND, AS WELL AS OTHER NON-CLIMATIC FACTORS.

THE BIDDER OR CONTRACTOR IS CAUTIONED THAT DETAILS SHOWN ON THE SUBSURFACE PLANS ARE PRELIMINARY ONLY AND IN MANY CASES THE FINAL DESIGN DETAILS ARE DIFFERENT, FOR BIDDING AND CONSTRUCTION PLANS AND DOCUMENTS FOR FINAL DESIGN INFORMATION ON THIS PROJECT. THE DEPARTMENT DOES NOT WARRANT OR GUARANTEE THE SUFFICIENCY OF ACCURACY OF THE PROSTICATION MADE, IND FINE THE PROPER TAINORS MADE, OR OPHION OF THE DEPARTMENT AS TO THE TYPE OF MATERIALS AND COMMITIONS TO BE ENCOUNTERED. THE BUDGER OR CONTRACTOR IS CAUTIONED TO MAKE SUCH INDEPENDENT SUBSURFACE INVESTIGATIONS AS HE DEEMS NECESSARY TO SATISFY HAISELF AS TO CONDITIONS TO BE ENCOUNTERED ON THIS PROJECT. THE CONTRACTOR SHALL HAVE NO CLAIM FOR ADDITIONAL COMPENSATION OR FOR AN EXTENSION OF TIME FOR ANY REASON RESULTING FROM THE ACTUAL CONDITIONS ENCOUNTERED AT THE SITE DIFFERING FROM THIS SUBSURFACE INFORMATION.

NOTE - THE INFORMATION CONTAINED HEREIN IS NOT IMPLIED OR GUARANTEED BY THE N. C. DEPARTMENT OF TRANSPORTATION AS BEING ACCURATE NOR IT IS CONSIDERED TO BE PART OF THE PLANS, SPECIFICATIONS, OR CONTRACT FOR THE PROJECT.

NOTE - BY HAVING REQUESTED THIS INFORMATION THE CONTRACTOR SPECIFICALLY WAIVES ANY CLAIMS FOR INCREASED COMPENSATION OR EXTENSION OF TIME BASED ON DIFFERENCES BETWEEN THE CONDITIONS INDICATED HEREIN AND THE ACTUAL CONDITIONS AT THE PROJECT SITE.

DRAWN BY: M. BATTEN

PROJECT REFERENCE NO.	SHEET NO.
17BP.8.R.7	2

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS GEOTECHNICAL ENGINEERING UNIT SOIL AND ROCK LEGEND, TERMS, SYMBOLS, AND ABBREVIATIONS

	DESCRIPTIONS MAY INCLUDE COLOR OR COLOR COMBINATIONS (TAN, RED, YELLOW-BROWN, BLUE-GRAY). MODIFIERS SUCH AS LIGHT, DARK, STREAKED, ETC. ARE USED TO DESCRIBE APPEARANCE.										X		E BIT	UGI	ER		VANE SHEAR TEST									
	MED. PLASTICITY 16-25 MEDIUM HIGH PLASTICITY 26 OR MORE HIGH COL OR						PORTABLE HOIST TRICONE STEEL TEETH POST HOLE DIGGE X CMF-55 TRICONE TUNGCARB. HAND AUGER				POST HOLE DIGGER															
PLASTICITY INDEX (PI) ORY STRENGTH NONPLASTIC 0-5 VERY LOW LOW PLASTICITY 6-15 SLIGHT								550			1	GCARBIDE		ERTS ADVANCER		-H										
PLASTICITY							BK-51]-B <u> </u>														
OM SL	REQUIRES ADDITIONAL WATER 1					ILE B			CLAY BITS 6° CONTINUOUS FLIGHT AUGER					AUTOMATIC MANUA	AL											
(PI) PL	Τ	ASTIC		•								TIMUM MOI		W0107:	DRILL U	INI 1	TS:	EUU			NG TOOLS:	<u> </u>	JUDJELI P	НА	AMMER TYPE:	
PLASTIC F	+ 110	OUID I	_IMIT				::., :T - ((w)		SE	MISOLIC	REQUIRES	DRYING T				FRAGMENTS	5		T	CR - TRIC	ONE		י חפי	(FCT	
(ATTE	RBERG	_IMITS	5)			SATU				US	UALLY I	_IQUID; VER	Y WET, USI	UALLY	e - VOID RATIO SAP SAPROLITIC F - FINE SD SANDY FOSS FOSSILIFEROUS SL SILTY FRACT FRACTURED, FRACTURES SLI SLIGHTLY											
SOIL	MOISTU	SOI RE SC	ALE		F)	IELD	MOIST	TURE	<u>.AT</u>			TERMS	STUBE OF	SCRIPTION	CSE COARSE NP - NON PLASTIC γ - UNIT WEIGHT DMT - DILATOMETER TEST ORG ORGANIC γ_d - DRY UNIT WEIGHT DPT - DYNAMIC PENETRATION TEST PMT - PRESSUREMETER TEST											
(BLDR		(CO	B.)		(GR.)	2.		SAN (CSE.		0.2	SAN (F S	ן יי	(SL.) 0.00	(CL.)	BT - BI CL CI CPT - I	CO	ING TERMI Y INE PENETF	NATED	TEST	м м м	ED MED ICA MIC IOD MODI	IUM ACEI ERA1	ELY		V - VERY VST - VANE SHEAR TEST WEA WEATHERED	ı
OPENING (M	Т	СОВІ	BLE	Π	4.76 RAVEL	2.		COAR	SE	0.25	FINE	:	SILT	CLAY	ABBREVIATIONS AR - AUGER REFUSAL HI HIGHLY ## - MOISTURE CONTENT						_					
U.S. STD. SI	EVE SIZ	:E		TE	<u>ΧΤι</u>	JRE 1		<u>GR</u>		1 S	200	270				SOUNDING ROD (REP)— SPT REFUSAL					RATIO SAMELE					
GENERALLY SOFT SILT-CLAY MEDIUM STIFF MATERIAL STIFF (COHESIVE) VERY STIFF HARD						2 TO 4 4 TO 8 8 TO 15 15 TO 30 >30				0.25 TO 0.50 0.5 TO 1.0 1 TO 2 2 TO 4 >4			25/025	• 1	INFERRED ALLUVIAL DIP & DIP ROCK STRU	SOIL BO	OUNDAR			,	PIEZOMETER INSTALLATION SLOPE INDICATO INSTALLATION)R	RT - RECOMPACTED TRIA SAMPLE CBR - CALIFORNIA BEARI RATIO SAMPLE			
VERY DENSE >50 VERY SOFT <2					<0.25			INFERRED SOIL BOUNDARY MW MONITORING W			MONITORING WE	LL	ST - SHELBY TUBE SAMPLE RS - ROCK SAMPLE													
GENER GRANU MATER	ILAR RIAL			VERY LO LOOSE MEDIUM DENSE	DENS	E		4 TO 10 10 TO 30 N/A				SOIL SYMBOL AUGER BORING ARTIFICIAL FILL (AF) OTHER THAN ROADWAY EMBANKMENT ————————————————————————————————————				AUGER BORING		SS - SPLIT SPOON SAMPLE								
PRIMARY	SOIL T	YPE		CONSIS	TENC		PEN	NE TRA	TION (N-VA	RESI	IDARD STENCE	COMPRE	OF UNCON SSIVE STI TONS/FT ²	RENGTH			ROADWAY E WITH SOIL			RE)	•	SPT OPT VST	OMT TEST BORIN	NG	SAMPLE DESIGNATIONS S - BULK SAMPLE	
PI	OF A-7	-5 SI	JBGR					OR	DEI	NSE	NESS	ROUP IS >			O-III	U		THE C			ELLANE	:OU	S SYMBOLS	3		
GEN. RATING AS A SUBGRADE		EXCEL	LEN1	TO GC	OD			F	AIR	TO F	POOR	FAIR TO POOR	POOR	UNSUITABLE				ERCHED PRING C			JRATED ZO	NE,	OR WATER BEAR	ING S1	IRATA	
USUAL TYPES OF MAJOR MATERIALS	STONE FR GRAVEL, A SAND	νn IF	INE AND	SIL TY GRAVE					.TY ILS		LAYEY	ORGAN MATTE		Joles	<u>▼</u>	_					E HOLE IN		IATELY AFTER I	DRILLI	NG	
GROUP INDEX	6 MX		NP 1	0 MX 10	MX 11	MN 11	\rightarrow			+	MX No M	LITTL MODER	E OR	HIGHLY ORGANIC SOILS	HIGHLY O	RG	ANIC		>10:	%	>20% GROUN	ND.	WATER	HLY	35% AND ABOVE	
= 200 Liquid Limit	15 MX 25	MX 16	MX :	10 MX 41	MN 40) MX 4	1 MN 4	10 MX	41 M	N 40	MX 41 MN	SOILS	SOILS	1.581	LITTLE O	RG	ORGANIC MA SANIC MATTI Y ORGANIC		SOII 2 - 1 3 - 1	3% 5%	501L9 3 - 52 5 - 12 12 - 20	: %	TRA LIT SOM	ACE TLE	1 - 10% 10 - 20% 20 - 35%	
	50 MX 30 MX 50			*********	2000 00	4.040	32.33	90000000				GRANULAR	SILT- CLAY	MUCK, PEAT	ORGA	MI	C MATERIAL		GRANU	ILAR	SILT - C	LAY	F MATERIA		r material	
CLASS. SYMBOL	A-1-a A	AAA	Í	4-2-4 A-	2-5 A	2 6 A	~		7.7		A-7-5 A-7-6	A-3	A-6, A-7			M	LIGHTLY CO ODERATELY	COMPR	ESSIBLE	•			LIQUID LIMIT LIQUID LIMIT LIQUID LIMIT	EQUAL	L TO 31-50	
CLASS.		≤ 35%		SSING .			(% PA		"200)	ORGA A-1, A-2	A-4. A-5				HEY ARE C			SIGNIF	FICANCE.		IBILITY			
SOIL LEGEND AND AASHTO CLASSIFICATION GENERAL GRANULAR MATERIALS SILT-CLAY MATERIALS CONTROL MATERIALS										MINERAL I	NΔ	MFS SIICH	AS OLIAF					COMPOSITIO		IN DESCRIPTIONS						
AS MINERAL		OMPOS	SITIO	, ANGUL	ARITY.	STRU	CTURE	, PLAS	STICI	TY, E	C. EXAM		CTORS SUCH	1	THE ANGULARITY OR ROUNDNESS OF SOIL GRAINS IS DESIGNATED BY THE TERMS ANGULAR, SUBROUNDED, OR ROUNDED.											
THAT CAN BE PENETRATED WITH A CONTINUOUS FLICHT POWER AUGER, AND VIELD LESS THAN 100 BLOWS PER FOOT ACCORDING TO STANDARD PENETRATION TEST (AASHTO T206, ASTM D-1586), SOIL CLASSIFICATION IS BASED ON THE AASHTO SYSTEM, BASIC DESCRIPTIONS GENERALLY SHALL INCLUDE: CONSISTENCY, COLOR, TEXTURE, MOISTURE, AASHTO CLASSIFICATION, AND OTHER PERTIMENT FACTORS SUCH								POORLY GRADED: GAP-GRADED - INDICATES A MIXTURE OF UNIFORM PARTICLES OF TWO OR MORE SIZES. ANGULARITY OF GRAINS																		
SOIL DESCRIPTION SOIL IS CONSIDERED TO BE THE UNCONSOLIDATED, SEMI-CONSOLIDATED, OR WEATHERED EARTH MATERIALS								GRADATION WELL GRADED - INDICATES A GOOD REPRESENTATION OF PARTICLE SIZES FROM FINE TO COARSE. UNIFORM - INDICATES THAT SOIL PARTICLES ARE ALL APPROXIMATELY THE SAME SIZE. (ALSO																		

PROJECT REFERENCE NO.	SHEET NO.
17BP.8.R.7	2A

NORTH CAROLINA DEPARTMENT OF TRANSPORTATION

DIVISION OF HIGHWAYS

GEOTECHNICAL ENGINEERING UNIT

SOIL AND ROCK LEGEND, TERMS, SYMBOLS, AND ABBREVIATIONS


-			BUCK (PECCHIPTION	TERMS AND DEFINITIONS						
HARD ROCK	IS NON-	COASTAL PLA		DESCRIPTION IF TESTED, WOULD YIELD SPT REFUS							
ROCK LINE	INDICATE	S THE LEVEL	AT WHICH NON-C	OASTAL PLAIN MATERIAL WOULD YIELD	ALLUVIUM (ALLUV.) - SOILS THAT HAVE BEEN TRANSPORTED BY WATER.						
IN NON-CO	ASTAL PL	AIN MATERIAL	r a SPLII SPUUN .• THE TRANSITIO	SAMPLER EQUAL TO OR LESS THAN 0. N BETWEEN SOIL AND ROCK IS OFTEN	REPRESENTED BY A ZONE	ADUIFER - A WATER BEARING FORMATION OR STRATA,					
OF WEATHE			DIVIDED AS FOLL	UMC.		ARENACEOUS - APPLIED TO ROCKS THAT HAVE BEEN DERIVED FROM SAND OR THAT CONTAIN SAND.					
WEATHERED ROCK (WR)	KIALS AF		NON-COASTAL PL	AIN MATERIAL THAT WOULD YIELD SP	T N VALUES > 100	ARGILACEOUS - APPLIED TO ALL ROCKS OR SUBSTANCES COMPOSED OF CLAY MINERALS, OR HAVING A NOTABLE PROPORTION OF CLAY IN THEIR COMPOSITION, AS SHALE, SLATE, ETC.					
CRYSTALLINE		7.7		GRAIN IGNEOUS AND METAMORPHIC RO T REFUSAL IF TESTED. ROCK TYPE IN		ARTESIAN - GROUND WATER THAT IS UNDER SUFFICIENT PRESSURE TO RISE ABOVE THE LEVEL AT WHICH IT IS ENCOUNTERED, BUT WHICH DOES NOT NECESSARILY RISE TO OR ABOVE THE GROUND SURFACE.					
ROCK (CR)			GNEISS, GABBRO,		ICLODES CHARITE,	CALCAREOUS (CALC.) - SOILS THAT CONTAIN APPRECIABLE AMOUNTS OF CALCIUM CARBONATE.					
NON-CRYSTALI ROCK (NCR)	LINE		SEDIMENTARY RO	GRAIN METAMORPHIC AND NON-COASTA CK THAT WOULD YEILD SPT REFUSAL ITE, SLATE, SANDSTONE, ETC.		COLLUVIUM - ROCK FRAGMENTS MIXED WITH SOIL DEPOSITED BY GRAVITY ON SLOPE OR AT BOTTOM OF SLOPE.					
COASTAL PLAI SEDIMENTARY (CP)	in Rock		COASTAL PLAIN S	SEDIMENTS CEMENTED INTO ROCK, BUT OCK TYPE INCLUDES LIMESTONE, SANDS		CORE RECOVERY (REC.) - TOTAL LENGTH OF ALL MATERIAL RECOVERED IN THE CORE BARREL DIVIDED BY TOTAL LENGTH OF CORE RUN AND EXPRESSED AS A PERCENTAGE.					
1017				THERING		<u>DIKE</u> - A TABULAR BODY OF IGNEOUS ROCK THAT CUTS ACROSS THE STRUCTURE OF ADJACENT					
	DOC# 55	DECLI COVETAL			CV DINCC UNDED	ROCKS OR CUTS MASSIVE ROCK.					
FRESH	HAMMER	IF CRYSTALL	INE.	INTS MAY SHOW SLIGHT STAINING, ROO		\underline{DIP} - THE ANGLE AT WHICH A STRATUM OR ANY PLANAR FEATURE IS INCLINED FROM THE HORIZONTAL.					
VERY SLIGHT	CRYSTAL		EN SPECIMEN FAC	ED. SOME JOINTS MAY SHOW THIN CLA' E SHINE BRIGHTLY. ROCK RINGS UNDER		<u>OIP DIRECTION (DIP AZIMUTH)</u> - THE DIRECTION OR BEARING OF THE HORIZONTAL TRACE OF THE LINE OF DIP, MEASURED CLOCKWISE FROM NORTH,					
SLIGHT (SLI.)	ROCK GE	NERALLY FRE	SH, JOINTS STAINE	ED AND DISCOLORATION EXTENDS INTO		FAULT - A FRACTURE OR FRACTURE ZONE ALONG WHICH THERE HAS BEEN DISPLACEMENT OF THE SIDES RELATIVE TO ONE ANOTHER PARALLEL TO THE FRACTURE.					
	CRYSTAL	S ARE DULL	AND DISCOLORED.	CRYSTALLINE ROCKS RING UNDER HAM	MER BLOWS.	FISSILE - A PROPERTY OF SPLITTING ALONG CLOSELY SPACED PARALLEL PLANES.					
MODERATE (MOD.)	GRANITO	ID ROCKS, MOS	ST FELDSPARS ARI	DISCOLORATION AND WEATHERING EFFE E DULL AND DISCOLORED, SOME SHOW	CLAY. ROCK HAS	${ ilde { m FLOAT}}$ - ROCK FRAGMENTS ON SURFACE NEAR THEIR ORIGINAL POSITION AND DISLODGED FROM PARENT MATERIAL.					
	WITH FR	RESH ROCK.		SHOWS SIGNIFICANT LOSS OF STREN		FLOOD PLAIN (FP) - LAND BORDERING A STREAM, BUILT OF SEDIMENTS DEPOSITED BY THE STREAM.					
MODERATELY SEVERE (MOD. SEV.)	AND DIS	COLORED AND	A MAJORITY SHOW	OR STAINED, IN GRANITOID ROCKS, AL W KAOLINIZATION, ROCK SHOWS SEVERI GIST'S PICK, ROCK GIVES "CLUNK" SOUN	E LOSS OF STRENGTH	<u>FORMATION (FM.)</u> - A MAPPABLE GEOLOGIC UNIT THAT CAN BE RECOGNIZED AND TRACED IN THE FIELD.					
			LD SPT REFUSAL			JOINT - FRACTURE IN ROCK ALONG WHICH NO APPRECIABLE MOVEMENT HAS OCCURRED.					
(SEV.)	IN STRE	NGTH TO STR	ONG SOIL. IN GRA	OR STAINED. ROCK FABRIC CLEAR AND NITOID ROCKS ALL FELDSPARS ARE KA		LEDGE - A SHELF-LIKE RIDGE OR PROJECTION OF ROCK WHOSE THICKNESS IS SMALL COMPARED TO ITS LATERAL EXTENT.					
			ENIS OF STRUNG PT N VALUES > 10	ROCK USUALLY REMAIN. 10 BPF		LENS - A BODY OF SOIL OR ROCK THAT THINS OUT IN ONE OR MORE DIRECTIONS.					
VERY SEVERE				OR STAINED. ROCK FABRIC ELEMENTS		MOTTLED (MOT.) - IRREGULARLY MARKED WITH SPOTS OF DIFFERENT COLORS. MOTTLING IN SOILS USUALLY INDICATES POOR AERATION AND LACK OF GOOD DRAINAGE.					
(V SEV.)	REMAINI	NG. SAPROLITE	IS AN EXAMPLE	D SOIL STATUS, WITH ONLY FRAGMENTS OF ROCK WEATHERED TO A DEGREE S IC REMAIN. <i>IF TESTED, YIELDS SPT</i>	UCH THAT ONLY MINOR	PERCHED WATER - WATER MAINTAINED ABOVE THE NORMAL GROUND WATER LEVEL BY THE PRESENCE OF AN INTERVENING IMPERVIOUS STRATUM.					
COMPLETE				NOT DISCERNIBLE OR DISCERNIBLE ON		RESIDUAL (RES.) SOIL - SOIL FORMED IN PLACE BY THE WEATHERING OF ROCK.					
				AY BE PRESENT AS DIKES OR STRING		ROCK QUALITY DESIGNATION (ROD) - A MEASURE OF ROCK QUALITY DESCRIBED BY TOTAL LENGTH OF					
	ALSO AN	EXAMPLE.	BUCK	HADDNECC		ROCK SEGMENTS EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF CORE RUN AND EXPRESSED AS A PERCENTAGE.					
VERY HARD			ED BY KNIFE OR	HARDNESS SHARP PICK, BREAKING OF HAND SPEC	IMENS REQUIRES	SAPROLITE (SAP.) - RESIDUAL SOIL THAT RETAINS THE RELIC STRUCTURE OR FABRIC OF THE PARENT ROCK.					
l			S OF THE GEOLOG		50. Di OUG 050:::050	SILL - AN INTRUSIVE BODY OF IGNEOUS ROCK OF APPROXIMATELY UNIFORM THICKNESS AND					
HARD	TO DET	TACH HAND SP	ECIMEN.	ONLY WITH DIFFICULTY, HARD HAMME		RELATIVELY THIN COMPARED WITH ITS LATERAL EXTENT, THAT HAS BEEN EMPLACED PARALLEL TO THE BEDDING OR SCHISTOSITY OF THE INTRUDED ROCKS.					
MODERATELY HARD	EXCAVA		BLOW OF A GEOL	G. GOUGES OR GROOVES TO 0.25 INCHE OGIST'S PICK. HAND SPECIMENS CAN I		SLICKENSIDE - POLISHED AND STRIATED SURFACE THAT RESULTS FROM FRICTION ALONG A FAULT OR SLIP PLANE.					
MEDIUM HARD	CAN BE	GROOVED OR	GOUGED 0.05 INC	HES DEEP BY FIRM PRESSURE OF KNI		STANDARD PENETRATION TEST (PENETRATION RESISTANCE) (SPT) - NUMBER OF BLOWS (N OR BPF) OF A 140 LB, HAMMER FALLING 30 INCHES REQUIRED TO PRODUCE A PENETRATION OF 1 FOOT INTO SOIL WITH					
SOFT	POINT	OF A GEOLOG	IST'S PICK.	BY KNIFE OR PICK. CAN BE EXCAVATE		A 2 INCH OUTSIDE DIAMETER SPLIT SPOON SAMPLER, SPT REFUSAL IS PENETRATION EQUAL TO OR LESS THAN 0.1 FOOT PER 60 BLOWS.					
	FROM (CHIPS TO SEV		SIZE BY MODERATE BLOWS OF A PICK		STRATA CORE RECOVERY (SREC.) - TOTAL LENGTH OF STRATA MATERIAL RECOVERED DIVIDED BY TOTAL LENGTH OF STRATUM AND EXPRESSED AS A PERCENTAGE.					
VERY SOFT	OR MOF	RE IN THICKNE		EXCAVATED READILY WITH POINT OF P IN BY FINGER PRESSURE. CAN BE SCR		STRATA ROCK QUALITY DESIGNATION (SROD) - A MEASURE OF ROCK QUALITY DESCRIBED BY TOTAL LENGTH OF ROCK SEGMENTS WITHIN A STRATUM EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF STRATA AND EXPRESSED AS A PERCENTAGE.					
FF	FINGER	RE SPACI	ING I	BEDDING		TOPSOIL (TS.) - SURFACE SOILS USUALLY CONTAINING ORGANIC MATTER.					
TERM			ACING	TERM	THICKNESS	BENCH MARK: BM*ISTA 10+65.88 -BL- 46.84' RT					
VERY WID		MORE TH	AN 10 FEET	VERY THICKLY BEDDED	> 4 FEET	RR SPIKE IN 15" BIRCH					
WIDE MODERATE		3 TO 10		THICKLY BEDDED THINLY BEDDED	1.5 - 4 FEET 0.16 - 1.5 FEET	ELEVATION: 302.29 FT.					
CLOSE		E 1 TO 3 F 0.16 TO		VERY THINLY BEDDED	0.03 - 0.16 FEET	NOTES:					
VERY CLO	SE		IAN Ø.16 FEET	THICKLY LAMINATED 0 THINLY LAMINATED	0.008 - 0.03 FEET < 0.008 FEET	NOTES:					
			INDI	JRATION							
FOR SEDIMENT	ARY ROCK	KS, INDURATION		NG OF THE MATERIAL BY CEMENTING,	HEAT, PRESSURE, ETC.						
	IABLE		RUBBING	WITH FINGER FREES NUMEROUS GRAIN: BLOW BY HAMMER DISINTEGRATES SAM	S;						
мог	DERATELY	INDURATED	GRAINS C	AN BE SEPARATED FROM SAMPLE WITH							
			BHEAKS E	SASILY WHEN HIT WITH HAMMER.							


GRAINS ARE DIFFICULT TO SEPARATE WITH STEEL PROBE: DIFFICULT TO BREAK WITH HAMMER.

SHARP HAMMER BLOWS REQUIRED TO BREAK SAMPLE; SAMPLE BREAKS ACROSS GRAINS.

INDURATED

EXTREMELY INDURATED






ONE COMPANY | Many Solutions sa

Boring Location Plan
Drawing No.: 2

County: Lee


7/30/12

NCDOT BORE SINGLE LEENO36.GPJ NC DOT.GDT




7/30/12


NCDOT BORE SINGLE LEENO36.GPJ NC DOT.GDT



ACDOT BORE SINGLE LEEN036.GPJ NC DOT.GDT 7/30/12



NCDOT BORE SINGLE LEEN036.GPJ NC DOT.GDT 7/30/12



SHEET	1	



FIELD SCOUR REPORT

WBS: 17BP.8.R.7 TIP: SF-520036 COUNTY: Lee											
DESCRIPTION(1): Replacement of Maintenance Bridge No. 36 on Sheriff Watson Rd. (SR 1165) over J	Juniper Creek										
EXISTING BRIDGE											
Information from: Field Inspection X Microfilm (reel pos:) Other (explain) Bridge Survey and Hydraulic Design Report)										
Bridge No.: 36 Length: 34.8 Total Bents: 3 Bents in Channel: 1 Bents in Foundation Type: Abutment walls, timber piles with concrete bases	loodplain: 2										
EVIDENCE OF SCOUR(2) Abutments or End Bent Slopes: Moderate scour observed at south abutment wall											
Interior Bents: Moderate scour observed (deepening and widening)											
Channel Bed: Moderate scour observed in channel bed (deepening and widening)											
Channel Bank: Moderate scour observed on south side											
EXISTING SCOUR PROTECTION											
Type(3): Vertical timbers under bridge deck and wing walls											
Extent(4): Approximately 4 ft past edge of bridge on upstream and downstream sides											
Effectiveness(5): Scour protection seems to be working											

INSTRUCTIONS

- 1 Describe the specific site's location, including route number and body of water crossed.
- 2 Note scour evidence at existing end bents or abutments (e.g. undermining, sloughing, degradations).
- 3 Note existing scour protection (e.g. rip rap).

Obstructions(6): No obstructions evident

- 4 Describe extent of existing scour protection.
- **5** Describe whether or not the scour protection appears to be working.
- 6 Note obstructions such as dams, fallen trees, debris at bents, etc.
- 7 Describe the channel bed material based on observation and/or samples. Include any lab results with report.
- 8 Describe the channel bank material based on observation and/or samples. Include any lab results with report.
- 9 Describe the material covering the banks (e.g. grass, trees, rip rap, none).
- 10 Determine the approximate floodplain width from field observation or a topographic map.
- 11 Describe the material covering the floodplain (e.g. grass, trees, crops).
- 12 Use professional judgement to specify if the stream is degrading, aggrading, or static.
- 13 Describe potential and direction of the stream to migrate laterally during the bridge's life (approx. 100 years).
- 14 Give the design scour elevation (DSE) expected over the life of the bridge (approx. 100 years). This elevation can be given as a range across the site, or for each bent. Discuss the relationship between the Hydraulics Unit theoritical scour and the DSE. If the DSE is dependent on scour counter measures, explain (e.g. rip rap armoring on slopes). The DSE is based on the erodability of materials, giving consideration to the influence of joints, foliation, bedding characteristics, % core recovery, % RQD, differential weathering, shear strength, observations at existing structures, other tests deemed appropriate, and overall geologic conditions at the site.

SHEET	2
SHEET	

Form GEU-017e Revised 7/26/2007

DESIGN INFORMATION													
Channel Bed Material(7): Silty fine SAND (A-2-4)													
Channel Bank Material(8): Silty fine SAND (A-2-4)													
Channe	Channel Bank Cover(9): Dense low vegetation, no trees in R/W, dense forest past R/W												
Flood	Floodplain Width(10): Approx. 150 ft on upstream and downstream												
Floodplain Cover(11): Dense low vegetation, no trees in ROW, dense forest past ROW													
	Strear	m is(12):	Ą	ggrading		Degra	ading _	X	Sta	atic	_		
Channel Migratio	n Tende	ncy(13):	Southwa	ard									
Observations	and Oth	er Comm	nents: No	one									
DESIGN SCO	UR ELE	VATION	S(14)				Fee	t X	Met	ers	_		
		BENTS											
	NA												
Comparison of	f DSE to	Hvdrauli	ics Unit th	heoretica	ıl scour:								
DSE is assum						ur.							
SOIL ANALYS	SIS RES	ULTS FF	ROM CH	ANNEL I	BED ANI	BANK	MATER	IAL					
Bed or Bank													
Sample No.											1		
Retained #4											1		
Passed #10 Passed #40													
Passed #200													
Coarse Sand													
Fine Sand													
Silt													
Clay													
LĹ													
PI													
AASHTO											1		
Station											1		
Offset				_							_		
Depth											1		



Photo 1: Looking North along -L-



Photo 2: Looking South at EB1-A



Photo 3: Looking South at EB2-A



Photo 4: Looking Downstream (East) towards Bridge No. 36

